SHARE CHARLES	APPENDIX C CODE CHANGE PROP NORTH CAROLINA BUILDING CODE COU 325North Salisbury Street, Room 5_44 Raleigh, North Carolina 27603 (919) 647-0009 carl.martin@ncdoi.gov	
Granted by BCC Denied by BCC	Petition for Rule Adopted by BCC Disapproved by BCC	Making       Item Number         Approved by RRC         Objection by RRC
PROPONENT: <u>Car</u> REPRESENTING: NC	l Martin DOI	PHONE: (919) 888-0284
ADDRESS: 1202 Mail		
CITY: Raleigh	STATE: NC	ZIP: <u>27699</u>
E-MAIL: carl.martin	@ncdoi.gov	FAX: ()
North Carolina State Bu	ilding Code, Volume <u>Building Cod</u>	e - Section 3006.2
CHECK ONE: [X] Re	vise section to read as follows: [	<ul><li>] Delete section and substitute the following:</li><li>] Delete section without substitution:</li></ul>
LINE THROUGH MATE	RIAL TO BE DELETED	NDERLINE MATERIAL TO BE ADDED

Please type. Continue proposal or reason on plain paper attached to this form. See reverse side for instructions.

**3006.2 Hoistway opening protection required.** Elevator hoistway door openings for occupied and unoccupied stories shall be protected in accordance with Section 3006.3 where an elevator hoistway connects more than three *stories*, is required to be enclosed within a *shaft enclosure* in accordance with Section 712.1.1 and any of the following conditions apply:

- 1. The building is not protected throughout with an *automatic sprinkler system* in accordance with Section 903.3.1.1 or 903.3.1.2.
- 2. The building contains a Group I-1, Condition 2 occupancy.
- 3. The building contains a Group I-2 occupancy.
- 4. The building contains a Group I-3 occupancy.
- 5. The building is a high rise and the elevator hoistway is more than 75 feet (22 860 mm) in height. The height of the hoistway shall be measured from the *lowest floor* to the highest floor of the floors served by the hoistway.

## **Exceptions:**

- 1. Protection of elevator hoistway door openings is not required where the elevator serves only *open parking* garages in accordance with Section 406.5.
- 2. Protection of elevator hoistway door openings is not required at the level(s) of exit discharge, provided that the level(s) of exit discharge is equipped with an *automatic sprinkler system* in accordance with Section 903.3.1.1.
- 3. Enclosed elevator lobbies and protection of elevator hoistway door openings are not required on levels where the elevator hoistway opens to the exterior.

Will this proposal change the cost of construction?	Decrease [ ]	Increase [ ]	No	[X]
---	--------------	--------------	----	-----

Will this proposal increase to the cost of a dwelling by \$80 or more?	Yes []	No	[X]
Will this proposal affect the Local or State funds? Local [ ]	State [ ]	No	[X]
Will this proposal cause a substantial economic impact ( $\geq$ \$1,000,000)?	Yes []	No	[X]
New Schetential Dravids on according to a chain in the diag has stitled to attention			

- Non-Substantial Provide an economic analysis including benefit/cost estimates.
- Substantial The economic analysis must also include 2-alternatives, time value of money and risk analysis.
- Pursuant to §143-138(a1)(2) a cost-benefit analysis is required for all proposed amendments to the NC Energy Conservation Code. The Building Code Council shall also require same for the NC Residential Code, Chapter 11.

**REASON:** Addressing unfinished or unoccupied stories that would require such protection for occupied stories clarifies and prevents the possibility of smoke and hot gases from those vacant stories from entering the elevator shaft.

BCC CODE CHANGES Signature: <u>*Alfati*</u> Date: <u>7/21/2021</u> FORM 11/26/19