# NC Department of Insurance Office of the State Fire Marshal - Engineering Division 1202 Mail Service Center, Raleigh, NC 27699-1202 919-647-0000

#### **Cross Ventilation in Porches**

Code: 2018 Residential Code Date: May 2, 2019

**Section:** R806.2

### **Ouestion:**

Is cross ventilation required in the spaces enclosed by a porch roof?

#### **Answer:**

Yes, but Section R806.2 Exception 2 is expected to provide sufficient cross ventilation for the unconditioned space above a porch.

#### **Reference:**

## **Section R806.2 – Minimum vent area, Exception #2:**

2. Enclosed attic/rafter spaces over unconditioned space may be vented with continuous soffit vent only.