## **INFORMAL CODE INTERPRETATION**

# NC Department of Insurance Office of the State Fire Marshal - Engineering Division 1202 Mail Service Center, Raleigh, NC 27699-1202 919-661-5880

## **Cross Ventilation in Porches**

Code: 2012 Residential Code Section: R806.2

Date: July 3, 2012

#### **Question:**

Is cross ventilation required in the spaces enclosed by a porch roof?

#### Answer:

See Section R806.2 Exception 2: "Enclosed attic/rafter spaces over unconditioned space may be vented with continuous soffit vent only."